

Work Order ID 71835

Wednesday, July 13, 2011 10:18:31 AM



Page 1

Item ID: D2745

Accept



Setup Start



Revision ID:

Stop



Item Name: Bushing

Start Date: 7/14/2011 Start Qty: 160.00



Cust Item ID:

Required Date: 7/28/2011 Req'd Qty: 160.00



Customer:

Reference:

Approvals: Process Plan: UMC Date: 11-07-13

Tooling:

Date:

Run Start



QC: Date:

SPC (Y/N):

Date:

Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D2745	Rev B								

100

0.00



Hardinge CNC LATHE SMALL

Hardinge

Memo

0.00

Hardinge CNC Lathe Small

1-Turn as per Dwg D2515-2-Deburr

SL 11/17/15

162

110

0.00



QC2- Inspect parts off machine FAI/FAIB

QC

Memo

0.00

Quality Control

CA 11/17/15

162

120

0.00



QC8- Inspect parts - second check

QC

Memo

0.00

Quality Control

B.A 11/07/19

162

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 71835

Wednesday, July 13, 2011 10:18:31 AM

Page 2

Item ID: D2745

Accept

Setup Start

Revision ID:

Stop

Item Name: Bushing

Start Date: 7/14/2011 Start Qty: 160.00

Cust Item ID:

Required Date: 7/28/2011 Req'd Qty: 160.00

Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop

Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

130

Identify as per dwg & Stock Location: *ad*

0.00



Packaging

Memo

0.00

Packaging

140

QC21- Final Inspection - Work Order Release

0.00



QC

Memo

0.00

Quality Control

Run 22 *162*

11/7/20

MF

11-07-20

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Wednesday, July 13, 2011 10:18:27 AM

Page 1

Work Order ID: 71835



Parent Item: D2745



Parent Item Name: Bushing

Start Date: 7/14/2011

Required Date: 7/28/2011

Start Qty: 160.00

Required Qty: 160.00

Comments: IPP ☐ C ☐ 02.03.07 ☐ Update to turn in house ☐ NG ☐
IPP Rev:D 07-10-23 Removed tumbling JLM Verified By:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M303R0.750 		Purchased		No		100	f	75.4700	0.0959	16.15158			

303 Round Bar 0.750

Location

MAT028

117328

117798

Loc Qty

75.47

36.97

38.5

Loc Code

11/7/18
16

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____


NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries



DESIGN <i>DA</i>	DRAWN BY <i>GP</i>	DART AEROSPACE USA, INC. FAIRCHILD INTERNATIONAL AIRPORT, WA	
CHECKED <i>DA</i>	APPROVED <i>KE</i>	DRAWING NO. D2745	REV. B SHEET 1 OF 1
DATE 98.10.23		TITLE BUSHING	SCALE 2:1
A	98.04.16	NEW ISSUE	
B	98.10.23	DIM 0.400 WAS 0.380	

RELEASED
98.11.03 DS



#71835

MATERIAL: AISI 303 STAINLESS STEEL

NOTES: TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
RADIUS ALL INSIDE EDGES 0.005 TO 0.010
BREAK ALL UNMARKED SHARP EDGES 0.010 TO 0.020
ALL DIMENSIONS ARE IN INCHES

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries